



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: Northwest
Photo by: Chris
Cahnovsky
Exposure #: 001
Comments: Material
removed from
around the furnace



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: Southwest
Photo by: Chris
Cahnovsky
Exposure #: 002
Comments:



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: Southwest
Photo by: Chris
Cahnovsky
Exposure #: 003
Comments: Material
removed from
around the furnace
and foundry floor



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: West
Photo by: Chris
Cahnovsky
Exposure #: 004
Comments: Material
removed from
around the furnace
and foundry floor



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 005
Comments:



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: Northeast
Photo by: Chris
Cahnovsky
Exposure #: 006
Comments: Open
wall to access office
spaces



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 007
Comments: Floor
area around
furnace cleaned up



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: West
Photo by: Chris
Cahnovsky
Exposure #: 008
Comments: Furnace
clean up solids



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg




Date: 7/22/2011
Time: 10:50 – 11:30
Direction: Southeast
Photo by: Chris
Cahnovsky
Exposure #: 009
Comments: Open
wall to access office
spaces and office
equipment



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 010
Comments: Open
wall to access office
spaces



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg




Date: 7/22/2011
Time: 10:50 – 11:30
Direction: North
Photo by: Chris Cahnovsky
Exposure #: 011
Comments: RCRA waste from second floor offices. Note that box is open



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: South
Photo by: Chris Cahnovsky
Exposure #: 012
Comments: broken transite panel



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg




Date: 7/22/2011
Time: 10:50 – 11:30
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 013
Comments: broken
transite panel




Date: 7/22/2011
Time: 10:50 – 11:30
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 014
Comments: broken
transite panel



DIGITAL PHOTOGRAPHS File Names: 1198010003~07222011-[Exp. #001-016].jpg



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: South
Photo by: Chris
Cahnovsky
Exposure #: 015
Comments: second
floor of foundry



Date: 7/22/2011
Time: 10:50 – 11:30
Direction: East
Photo by: Chris
Cahnovsky
Exposure #: 016
Comments: Broken
transite panel